United States of America

Department of Transportation—Jederal Aviation Administration

Supplemental Type Certificate

Number SA4385SW

Project T7061SW-DS RAD-191

This certificate, issued to Falcon Jet Corporation

P. O. Box 967

Little Rock, Arkansas 72203

cortifies that the change in the type design for the following product with the limitations and conditions therefor as specified hereon meets the airworthiness requirements of Parts 21.29 of the Federal Aviation Regulations.

Original Product - Type Certificate Number: A46EU

Avions Marcel Dassault - Breguet Aviation

Model:

Mystere - Falcon 50

Description of Type Design Change:

Installation of Sperry SPZ-600/SPI-501/SPI-502 Automatic Flight Control System for Category II operations:

- 1. With Electro/Mechanical Instrumentation
- With EFIS Instrumentation

Limitations and Conditions:

See Continuation Sheet 2 of this STC.

Compatibility of this modification with other previously approved modifications must be determined by the installer.

This certificate and the supporting data which is the basis for approval shall remain in effect until surrendered, suspended, revoked, or a termination date is otherwise established by the Administrator of the

Federal Aviation Administration.

Date of application: February 5, 1981

Date reissued :

Date of issuance:

June 17, 1981

Dale amended: 3/19/82; 6/17/85

Manager, Aircraft/Certification Division

Southwest Region

(Title)

Any alteration of this certificate is punishable by a fine of not exceeding \$1,000, or imprisonment not exceeding 3 years, or both.

United States of America

Department of Transportation—Federal Aviation Administration

Supplemental Type Certificate

(Continuation Sheet)

Number SA4285SW

Revision 2

Limitations and Conditions:

- 1. Sperry Automatic Flight Control System with Electro/Mechanical Instrumentation requires concurrent installation of STC's SA4312SW, SA4313SW, SA4286SW, SA4314SW (when required by FAR's) and SA4165SW (when required by FAR's) and FAA Approved Airplane Flight Manual Supplement Report No. 35150-2, Revision A dated April 25, 1985; or when VNAV is installed, Supplement Report No. 35150-4, Revision B dated March 17, 1983, is required.
- 2. Sperry Automatic Flight Control System with EFIS Instrumentation requires the concurrent installation of STC's SA4312SW, SA5415SW, SA5439SW, SA4286SW, SA4314SW (when required by FAR's) and SA4165SW (when required by FAR's) and FAA Approved Airplane Flight Manual Supplement Report No. 35150-6 dated June 17, 1985, is required.

INSTRUCTIONS: The transfer endorsement below may be used to notify to	the appropriate	FAA Regional	Office of
the transfer of this Supplemental Type Certificate.		J	

The FAA will reissue the certificate in the name of the transferee and forward it to him.

TRANSFER ENDORSEMENT

Transfer the ownership of Supplemental Type Cert	tificate Number
to (Name of transferee)	
(Address of transferee)	(Number and street)
	(City, State, and ZIP code)
from (Name of grantor) (Print or type)	
(Address of grantor)	(Number and street)
	(City, State, and ZIP code)
Extent of Authority (if licensing agreement):	
Date of Transfer:	
Signature of grantor (In ink):	